

**METAL/NONMETAL MINE FATALITY** — On January 8, 2015, a 63-year old sales manager with 11 years of experience was killed at a sand and gravel mine. He was installing new screen panels in the B tower screen. The feeder box pivoted, pinning him between the box and the rear support beam of the screen deck.



## **Best Practices**

- Establish and discuss safe work procedures. Identify and control all hazards associated with the work to be performed along with the methods to properly protect persons.
- Always follow the equipment manufacturer's recommended maintenance procedures when conducting repairs to machinery.
- Task train all persons to recognize all potential hazardous conditions and understand safe job procedures to eliminate all hazards before beginning work.
- Securely block equipment and components against hazardous motion at all times while performing work.
- Ensure that blocking material is competent, substantial, and adequate to support the load.
- Require all persons to be positioned to prevent them from being exposed to any hazards. Do not work in pinch points where inadvertent movement could cause injury.
- Monitor all persons to ensure safe work procedures, including safe work positioning, are followed.

This is the 1<sup>st</sup> fatality reported in calendar year 2015 in metal and nonmetal mining. As of this date in 2014, there were 0 fatalities reported in metal and nonmetal mining. This is the 1<sup>st</sup> Falling Material fatality in 2015. There were 0 Falling Material fatalities in the same period in 2014.